

NO. D-96-19
DATE June 1996

**Subject: WARRANTY COVERAGE EXTENSION
ON BENDIX 10 ABS COMPONENTS**

FOR: C/P/D dealer
 J/E dealer
 all dealers
 zone office
 field

This bulletin is issued to clarify dealer inquiries regarding the warranty coverage on certain ABS brake components.

Effective immediately, the warranty on Bendix 10 ABS components is extended to 10 years or 100,000 miles, whichever comes first. The ABS brake piston seal and pump motor assembly are extended to lifetime as per Recall #685. This extension applies to the vehicle regardless of ownership.

Bendix 10 ABS was used on 1990-1993 Chrysler New Yorker, Salon, Fifth Avenue, Imperial and Dodge Dynasty. 1991-1993 Chrysler Town & Country, Dodge Caravan / Grand Caravan and Plymouth Voyager / Grand Voyager. 1991-1992 Dodge Monaco and Eagle Premier.

NOTE: 1990 vehicles built through March 26, 1990 (MDH 03-26-XX) are equipped with a Bosch ABS brake system, and therefore are not included in the recall or the extended warranty.

The covered Labor Operations (LOP), LOP description and warranty coverage are as follows:

Labor Operation	Description	Coverage
05-25-25-01	Pressure/Return Hose Assembly, replace	10/100
05-30-17-02	Proportioning Valve w/switch, replace	10/100
05-40-07-02	Hydraulic Assembly, test & replace	Lifetime
05-40-07-93	Piston Assembly Actuator, replace (TSB 05-13-92 & 05-24-94)	Lifetime
05-40-25-02	Master Cylinder Reservoir, replace	10/100
05-45-04-01	Pump Supply Filter, replace	10/100
05-45-04-90	Pump Supply Filter, replace (TSB 05-24-94)	10/100
05-60-02-02	Pump/Motor Assembly, replace	Lifetime
05-60-03-01	Accumulator Assembly, replace	10/100
05-65-01-01	Primary Pressure Transducer, replace	10/100
05-45-03-90	Primary Pressure Transducer, replace (TSB 05-24-94)	10/100
05-65-02-01	Boost Pressure Transducer, replace	10/100
05-45-03-91	Boost Pressure Transducer, replace (TSB 05-24-94)	10/100

Reviewed by Service Manager Parts Manager Office Manager Other Page 1 of 2

05-67-01-01	Differential Pressure Switch, replace	10/100
05-45-02-90	Differential Pressure Switch, replace (TSB 05-24-94)	10/100
08-14-18-02	Right Front Wheel Speed Sensor, replace	10/100
08-14-18-03	Left Front Wheel Speed Sensor, replace	10/100
08-14-18-04	Right Rear Wheel Speed Sensor, replace	10/100
08-14-18-05	Left Rear Wheel Speed Sensor, replace	10/100
08-14-18-94	All Four Wheel Speed Sensors , inspect (TSB 05-10-93 Rev A)	10/100
08-14-18-95	One or Both Front Wheel Speed Sensors, replace (TSB 05-10-93 Rev A)	10/100
08-14-18-96	One or Both Rear Wheel Speed Sensors, replace (TSB 05-10-93 Rev A)	10/100
08-65-56-01	Pump/Motor Relay, replace	10/100
08-19-10-01	Controller Antilock Brake, replace	10/100
08-65-57-02	System Relay, replace	10/100
08-65-57-03	Warning Lamp Relay, replace	10/100
08-65-57-04	System/Warning Lamp Relay, replace	10/100
08-80-14-01	Dual Function Switch, replace	10/100
05-30-17-90	Dual Function Switch, replace (TSB 05-07-91)	10/100
08-90-70-01	Wiring Harness, replace	10/100
08-65-57-90	Wiring Jumper Harness Assembly (TSB 05-05-92)	10/100
05-50-01-91	Brake Pedal Return Spring Kit (TSB 05-08-92 Rev A)	10/100

This warranty extension also covers DRB III and MDS diagnosis if required.

Parts / repairs not listed above are excluded from this warranty extension. For example, basic brake system components such as calipers, brake pads, ... are excluded.

Before proceeding with repairs, technicians should review the recently released Service and Diagnostic Procedures Manual for Bendix Antilock 9 and 10 (Publication #81-699-96086). The new test fixture (Miller #6997) should be used to test and repair the Bendix system.

Customer notification of the Recall and Warranty extension will begin when an adequate supply of replacement parts are available.

Owners who have previously paid for a repair involving the covered parts described above within the extended warranty time period, are eligible for reimbursement consideration. To request reimbursement, owner's should send their original receipts, keeping a copy for their records to:

Chrysler Customer Center
P.O. Box 21-8004
Auburn Hills, MI 48321-8004
ATTENTION: Recall #685 Reimbursement

Should customers require further assistance regarding this issue, they should be directed to call 1-800-853-1403.

Please insure all dealership personnel are updated on this coverage extension.



W. W. Hostynski
Manager,
Warranty Administration

DLR5-306

Q & A

- Q: My vehicle was not repaired at a Chrysler Corporation dealership. Am I entitled to reimbursement consideration?
- A: Yes. If the repair was completed within the time and mileage limitations and involved Bendix 10 ABS components, a request should be submitted to Chrysler.
- Q: The pump motor assembly as well as the right front wheel speed sensor had to be replaced on my vehicle. Will the right front wheel speed sensor be included in any reimbursement consideration?
- A: Yes. All Bendix 10 ABS brake components that required replacement or repair will be included in any reimbursement consideration.
- Q: I was given a partial goodwill reimbursement by the District Manager for the ABS brake repair on my vehicle. Will consideration now be given for reimbursement of the complete repair?
- A: Yes. The portion of the ABS repair that was paid by the customer and not previously reimbursed will be considered.
- Q: I have since sold my vehicle but still have the bill for the ABS brake repairs. Am I still eligible for reimbursement?
- A: Yes. As long as an original, legible, paid receipt is submitted reimbursement will be considered.
- Q: I have lost my receipt. Can I still get a reimbursement?
- A: Yes. As long as documentation can be furnished for consideration. The repairing facility should be contacted to see if a duplicate paid receipt can be obtained. Canceled checks or credit card receipts should be submitted as further supporting documentation.
- Q: The calipers on my vehicle had to be replaced. Is this replacement eligible for reimbursement?
- A: No. Basic Brake system components such as calipers, brake pads or shoes and linings are not included.